

Motley - 22Y

1218 Highway 10 S, Motley, MN 56466



Airport Manager: Loren A. Morey - 218-352-6467 -
moreys@brainerd.net

Contact Person: Loren A. Morey - 218-352-6467 -
moreys@brainerd.net

AWOS/ASOS: None

MnWAS Loc/Hrs: None

Attended: Unattended

Available Fuel: None

FBO(s): None

Businesses: None

Ground Transport: None

Food Service: Morey Fish Company

Dining: Country Side Restaurant - 2 blocks

Lodging: Eastwood Inn

Airport Events: None reported

Underwing Camp: No


Campgrounds: None Reported

Local Attractions: Pine Ridge Golf Course - 4 miles South

Comments: Self-service fuel at Staples Airport
Not plowed in Winter

Field Elev: 1225' TPA: 2200' (975' AGL)

Motley - 22Y



SEC. CH: TWIN CITIES

LAT: 46-19-24.873N

LONG: 094-38-19.049W

Approaches: Visual Only

COMM: 122.9

CTR: 118.05 MSP



Morey's Airport